

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC K8E Pad**  
**Location #: 334798**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC K8E Pad**  
**Location #: 334798**



**Photo # 7808 Culvert needs maintenance (Culvert is near entrance to location)**



**Photo # 7809 Culvert needs maintenance (Culvert is near entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC K8E Pad**  
**Location #: 334798**



**Photo # 7810 Erosion & transport of sediment off location**



**Photo # 7811 Erosion & transport of sediment off location**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC K8E Pad**  
**Location #: 334798**



**Photo # 7812 Erosion & transport of sediment off location/choking off vegetation**



**Photo # 7813 Erosion & transport of sediment off location/choking off vegetation**