

Inspection Photos

API: 061-05145

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/15/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 5/15/2023

Inspection Photos



Photo 1. Facing south toward the access road. There has been soil hauled in to bring the road back to contour. Soils have been seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023

Inspection Photos



Photo 2. There has been soil hauled into bring the road back to contour. Soils have been seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023

Inspection Photos



Photo 3. Facing south toward the location which has been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023

Inspection Photos



Photo 4. The electric powerline which dead ends at the location must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023

Inspection Photos



Photo 6. The electric wire does not have any current flow down the line. No insulators were used on the wood posts.



Photo 7. The electric wire does not have any current flow down the line. No insulators were used on the wood posts. Another solar charger should be used for this long stretch of wire.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources