

Inspection Photos

API: 061-06041

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/15/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 5/15/2023

Inspection Photos



Photo 1. Facing west at the beginning of the access road. The cattleguard has been removed and the road regraded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 5/15/2023

Inspection Photos



Photo 2. Facing west toward the access road which has been reclaimed. There is a 1 strand electric fence around the reclaimed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 5/15/2023

Inspection Photos



Photo 3. Facing northwest toward the location which has been seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 5/15/2023

Inspection Photos



Photo 4. There was some seed germination seen in the mulch. Continue to monitor to ensure vegetation fully re-establishes.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 5/15/2023