

Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/15/2023



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 5/15/2023

Inspection Photos



Photo 1. Facing north along the access road. This portion of the road has not been recontoured and reclaimed. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 5/15/2023

Inspection Photos



Photo 2. Facing northwest toward the two access road to the former tank battery and wellsite. There has been soil hauled in to bring the road back to contour. Soils have been seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 5/15/2023

Inspection Photos



Photo 3. Facing northwest toward the former tank battery site located 300' southwest of the well site. Soils have been seeded and straw mulched. Straw mulch is sparse which will not



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 5/15/2023

Inspection Photos



Photo 4. Facing northeast toward the access road to the former wellsite. There has been soil hauled into bring the road back to contour. Soils have been seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 5/15/2023

Inspection Photos



Photo 5. Facing back south toward the access road. There has been soil hauled into bring the road back to contour for this portion of the road. Soils have been seeded and straw mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 5/15/2023