

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2023

Submitted Date:

05/17/2023

Document Number:

708900517

**FIELD INSPECTION FORM**Loc ID 334908 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263455	WELL	PR	08/17/2004	GW	045-08129	GM 22-12	PR
263456	WELL	PR	04/03/2002	GW	045-08131	GM 322-12	PR

**General Comment:****COGCC Inspection Report Summary**

On 05/17/2023 at approximately 12:15 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC GM 322-12 pad.

Location # 334908 in Garfield County Colorado.

Please refer to Inspection 708900067 conducted on 03/03/2023, previous corrective action has been completed.

Location is within High Priority/Density/NSO Habitat areas &amp; is approximately 150 yards from Parachute Creek.

Location is also on the edge of a rule 411a surface water external buffer.

While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/split pad - Wellheads only, all production equipment for these 2 wells is located at location # 311597

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road has been fenced off & tracking sign placed in the middle of the access road. No vehicle access to location at this time.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	322-12 well bradenhead equiped with a Taylor plug, bradenhead valve accessible. 22-12 well bradenhead no form of pressure monitoring equipment, bradenhead valve accessible.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	263455	Type:	WELL	API Number:	045-08129	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	263456	Type:	WELL	API Number:	045-08131	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
Compaction						
		Gravel				Sparse in some sections
Ditches						
Gravel						Sparse

Comment: Pad appears to have been bladed.

Access road has been fenced off & tracking sign placed in the middle of the access road.  
No vehicle access to location at this time.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Remote location/split pad - Wellheads only, all production equipment for these 2 wells is located at location # 311597	smelserw	05/17/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900518	Inspection 708900517 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117870">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117870</a>
708900519	Inspection 708900517 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117871">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117871</a>