

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2023

Submitted Date:

05/18/2023

Document Number:

700300557

**FIELD INSPECTION FORM**

Loc ID 333971 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
, General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268048	WELL	PR	05/21/2003	CBM	067-08818	JW WARD A 2	PR
298429	WELL	PR	06/14/2021	GW	067-09630	JW WARD A 4	PR

**General Comment:**

Compliance supervisor and compliance specialist Curtis Patillo confirmed removal of primary noise source and site conditions and compliance with noise levels related to complaint doc# 403199546.

We spoke with complainant who stated that with the compressor removed he no longer had issues with the noise coming from the location with just pumping units running and that it was alright to close his complaint.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Production equipment and PBV fenced with stock panels		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gathering Line	# 1		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)	cone top	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>			
Facility ID: <u>268048</u>	Type: <u>WELL</u>	API Number: <u>067-08818</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <input style="width: 90%;" type="text"/>			
Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 10%;" type="text"/>		
<b>BradenHead</b>			
Date of Last Brhd Test: <u>06/27/2022</u>	Annual Brhd Completed? <input style="width: 100px;" type="text"/>		
Last Brhd Test Results	Initial Surf Csg Pressure: <u>0</u>	Fluid Type: <input style="width: 150px;" type="text"/>	
	End Surf Csg Pressure: <u>0</u>		
Comment: <input style="width: 90%;" type="text"/>			
Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 10%;" type="text"/>		
Facility ID: <u>298429</u>	Type: <u>WELL</u>	API Number: <u>067-09630</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <input style="width: 90%;" type="text"/>			
Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 10%;" type="text"/>		
<b>Complaint</b>			
Comment: <u>Ok to close complaint 403199546 now that compressor has been rremoved</u>			
Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 10%;" type="text"/>		
<b>BradenHead</b>			
Date of Last Brhd Test: <u>07/06/2022</u>	Annual Brhd Completed? <input style="width: 100px;" type="text"/>		
Last Brhd Test Results	Initial Surf Csg Pressure: <u>14</u>	Fluid Type: <input style="width: 150px;" type="text"/>	
	End Surf Csg Pressure: <u>0</u>		
Comment: <input style="width: 90%;" type="text"/>			
Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 10%;" type="text"/>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300565	compressor removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117980">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117980</a>
700300566	wattles installed east side of location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117981">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6117981</a>