

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2023

Submitted Date:

05/18/2023

Document Number:

712700180

FIELD INSPECTION FORMLoc ID 325235 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fields, Vanessa		vfields@logosresourcesllc.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Regulatory@logosresourcesllc.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214370	WELL	TA	07/01/2020	GW	067-05781	ESPINOSA 1	TA

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.
Witness 5-year MIT.

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Present](#)

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Due to the well being designated "out of service" and it won't be brought back to production the equipment on site is no longer needed for ongoing oil and gas operations. Remove unused separator, meter run and tank per Rule 606.a		
Corrective Action:	Comply with Rule 606.a.	Date:	08/17/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	Open Top		37.015970,-107.510710	
Comment:	Open top stock tank, turned upside down.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214370	Type:	WELL	API Number:	067-05781	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
<div>Comment: <div>Perforated interval 5028'-5376'. Bridge plug or cement plug depth 4928'. Casing pressure start 369 lbs. Casing pressure - 5 min. 368 lbs. Casing pressure - 10 min. 367 lbs. Casing pressure final 367 lbs. See Photo #3.</div></div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700185	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6118002