

Inspection Photos

API: 05-061-06076

Operator: CHEMCO INC

Inspection Date: 5/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023

Inspection Photos



Photo 1. Facing southwest along the access road which has not been reclaimed. The crop has not re-established and there are undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023

Inspection Photos



Photo 2. Facing southwest at the location. There is equipment that still remains at the location. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023

Inspection Photos



Photo 3. Facing northwest at the location. There is equipment and a cement pad that still remains at the location. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023

Inspection Photos



Photo 4. Facing east at the location. This area approx. 75'x75' is bare of vegetation with no crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023

Inspection Photos



Photo 5. South side of the location facing north. This area approx. 75'x75' is bare of vegetation with no crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023

Inspection Photos



Photo 6. Facing east toward the surrounding undisturbed crop field. Wheat stubble is shown to be uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 5/15/2023