

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/12/2023

Document Number:

707800361

FIELD INSPECTION FORMLoc ID 324703 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 28780

Name of Operator: FAHEY OIL & GAS

Address: 93 SOUTH COUNTY ROAD 159

City: STRASBURG State: CO Zip: 80136

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		dnr_cogccengineering@state.co.us	engineering
fahey, dave	303-622-9495	diafahey07@aol.com	owner operator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212482	WELL	PR	05/01/2021	OW	057-06376	STATE 12-8	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 5/10/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Fahey state 12-8, at Location # 324703 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well pump jack not operating at time of inspection. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

During this inspection the following compliance issues were observed:

1. No BMP's installed to prevent sediment migration from occurring on location.
2. Location and access is covered with vegetation.
3. Lease road shows signs of lack of stabilization/compaction.
4. Access road to well is not marked or maintained
5. No API posted on well head
6. Lack of tank battery signage
7. Secondary containment is insufficient.
8. No evidence of Braden Head access.
9. Valves on tanks missing cap/plug

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well head lacking information		
Corrective Action:	Provide proper signage per the rule	Date:	06/23/2023
Type	BATTERY		
Comment:	Lack of tank battery signage		
Corrective Action:	Provide proper signage per the rule	Date:	06/23/2023

Emergency Contact Number:

Comment: 911/303-709-0148

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Valves on tanks missing caps/plugs		
Corrective Action:	Install caps/plugs	Date:	05/26/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	Oil well head		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	No evidence of Braden Head access.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection	Date:	05/22/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate			Inadequate	
Comment: Secondary containment is insufficient					
Corrective Action: Repair or install berms or other secondary containment devices					Date: 06/23/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	212482	Type:	WELL	API Number:	057-06376	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing according to data base, valves open.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1.No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.
 2. Location and access is covered with vegetation.
 3. Lease road shows signs of lack of stabilization/compaction.
 4. Access road to well is not marked or maintained

Corrective Action: **Install, maintain or repair required BMPs**

Date: 06/23/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403402391	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113828
707800367	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113820