

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148




SW Corner of Location – Photo #03610



NW Corner of Location – Photo #03611

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



NE Corner of Location – Photo #03612



SE Corner of Location – Photo #03613

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



Wellheads – Photo #03614



Separators – Photo #03616

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



Tank Battery – Photo #03617



Open-Ended Load Line – Photo #03622



TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



Open-Ended Load Line – Photo #03623



Open-Ended Load Line – Photo #03624

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



Lease Road Degradation – Photo #03628



Rill Erosion Transporting Sediment – Photo #03629

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



Sediment Trap Full & Needs Maintenance– Photo #03630



Rill Erosion Transporting Sediment – Photo #03632

TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/35NESE

Location #335148



Rill Erosion/Degradation – Photo #03623



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #03636