

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2023

Submitted Date:

05/22/2023

Document Number:

708900545

FIELD INSPECTION FORMLoc ID 335332 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263835	WELL	PR	08/27/2002	GW	045-08143	CLOUGH RMV 150-22	PR
293566	WELL	PR	07/20/2008	GW	045-15045	CLOUGH RWF 543-22	PR
294208	WELL	PR	07/31/2008	GW	045-15316	CLOUGH RWF 343-22	PR
294209	WELL	PR	01/07/2008	GW	045-15317	CLOUGH RWF 43-22	PR
294210	WELL	PR	01/07/2008	GW	045-15318	CLOUGH RWF 443-22	PR
294211	WELL	PR	07/27/2008	GW	045-15319	CLOUGH RWF 344-22	PR

General Comment:**COGCC Inspection Report Summary**

On 05/22/2023 at approximately 09:43 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 150-22 pad.

Location # 335332 in Garfield County Colorado.

Please refer to Inspection 700704234 conducted on 05/23/2022, previous corrective actions have been completed.

Location is within High Priority/Density/NSO Habitat areas & Bald Eagle Roost site as well as within close proximity to Bald Eagle Nest site.

Location is approximately 97 yards from the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/Split pad - Wellheads only, all production equipment for these 6 wells is located on the RMV 11-22 pad location # 335181

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead signs cracking & peeling but still legible.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 6		corrective date
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	

Type: Bradenhead	# 6		
Comment:	Taylor plugs located on all bradenhead, all bradenhead valves are accessible.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	263835	Type:	WELL	API Number:	045-08143	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	293566	Type:	WELL	API Number:	045-15045	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	294208	Type:	WELL	API Number:	045-15316	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	294209	Type:	WELL	API Number:	045-15317	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	294210	Type:	WELL	API Number:	045-15318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	294211	Type:	WELL	API Number:	045-15319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse
				Material Handling And Spill Prevention		Chemical tank containment
Gravel						Sparse in some areas
Compaction						
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Remote location/Split pad - Wellheads only, all production equipment for these 6 wells is located on the RMV 11-22 pad location # 335181	smelserw	05/22/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900546	Inspection 708900545 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121112
708900547	Inspection 708900545 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121113