

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2023

Submitted Date:

05/22/2023

Document Number:

693806072

**FIELD INSPECTION FORM**Loc ID 325606 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES LLC

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	SW Insp Reports
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215093	WELL	SI	02/01/2023	OW	067-06698	ANGELINA 4	PR

**General Comment:**

COGCC staff performed Optical Gas Imaging Survey inspection on 5/18/2023.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	215093	Type:	WELL	API Number:	067-06698	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Pumping								
Corrective Action:				Date:					

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 37.131341 Long: -108.094419Wind: Light Speed: 5-10 (mph) Direction From: W Weather: Partly Temperature: 75 (F)Assisting Staff: Tom Beardslee Camera #: 2☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:00	AM	11:15	AM	Wellhead(s)

Comment: Leaking gas at wellhead tubing casing flange.Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.Date: 06/01/2023**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693806074	FLIR Video MOV_3554	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121217">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121217</a>
693806090	Inspection photos 5/18/2023	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6121218</a>