

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278



Photo #1. View of Corrective Action identified in Doc. #712700059.



Photo #2. View of completed corrective action.

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278



Photo #3. View of Corrective Action identified in Doc. #712700059.

Photo #4. View of completed Corrective Action .

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278

Photo #1. Wellsite identification sign and emergency contact.

Photo #2. View of wellhead and flowline assembly.