

Inspection Photos

API: 043-06182

Operator: INCREMENTAL OIL & GAS
(FLORENCE) LLC

Inspection Date: 5/22/2023



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 1. Facing north along the access road. There is erosion that has occurred along the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 2. Facing northwest further along the access road. A recent storm event has created an erosion channel down the road which needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 3. Facing north at the drainage crossing along the road. Stormwater has caused erosion of the road and has washed gravel and sediment off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 4. Facing toward the culvert at the drainage crossing. The recent storm event directed stormwater past the culvert at the red arrow causing erosion further down the road shown in the next photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 5. There was significant erosion of the road that occurred from the recent storm event. There is an approximate 4' gully along the road side in this area. Red arrow points to 4.5 ft. shovel placed in the gully.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 6. Facing back to the area of the road that has been washed out. Red arrow points to the shovel shown in the same place as previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 7. Further north along the access road at the second drainage crossing. Stormwater flowed over the culvert in this area which washed up debris in this area that will need to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 8. The culvert at this drainage crossing has filled in with sediment and debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 9. Facing northeast along the access road near the location. Stormwater has caused an erosion channel along the road that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 10. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 11. Well sign is posted at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 12. East side of the location facing west. The location is not reclaimed and needs to be reduced in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 2. Facing toward the topsoil pile at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 14. Southeast side of the location facing northwest. The location is not reclaimed and needs to be reduced in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 15. There are undesirable weeds (Kochia sp.) throughout the location which will need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023

Inspection Photos



Photo 16. Southwest side of the location facing northeast. The location is not reclaimed and needs to be reduced in size. Gravel remains along unused areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06182 | Date: 5/22/2023