

# Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 5/22/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023

## Inspection Photos



**Photo 1.** Facing northeast at the abandoned well site. The location has not been reclaimed and soils are bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023



## Inspection Photos



**Photo 2.** There is an abandoned powerpole that remains which needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023



## Inspection Photos



**Photo 3.** There is guyline anchor cable that remains at the southeast side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023



## Inspection Photos



**Photo 4.** Facing southeast at the abandoned well site. The location has not been reclaimed and soils are bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023



## Inspection Photos



**Photo 5.** There is oil stained soils at center of location that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023



## Inspection Photos



**Photo 6.** There is another guyline anchor cable that remains at the southwest side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40001 | Date: 5/22/2023