

# Inspection Photos

API: 043-06124

Operator: JAVERNICK OIL

Inspection Date: 5/22/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023

## Inspection Photos



**Photo 1.** Facing south along the access road. There is erosion that occurred at the drainage crossing from recent storm event. The road has been washed out and needs to be repaired and BMP's need to be installed at the drainage crossing such as an adequately sized culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023



## Inspection Photos



**Photo 2.** There is erosion along the road side that needs to be repaired and stabilized with BMP's. Red arrow points to 4.5' shovel for scale. There is a long stretch from this point further along the road with no culverts to divert stormwater off the road. Additional BMP's need to be installed along the road.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023



## Inspection Photos



**Photo 3.** Facing back north at same area of erosion shown in previous photo. Stormwater and sediment is directed toward the creek drainage and needs to be repaired and stabilized to prevent erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023



## Inspection Photos



**Photo 4.** Further along the road is additional erosion on the road side that needs to be repaired and stabilized with BMP's.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023

## Inspection Photos



**Photo 5.** Facing northwest toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023



## Inspection Photos



**Photo 6.** There is oil stained soils at back side of tanks shown at red arrows.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023

## Inspection Photos



**Photo 7.** Facing northeast toward the wellsite. There is vehicle rutting at the location which is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06124 | Date: 5/22/2023