

# Interim Reclamation and Stormwater Inspection

Date: 05/17/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 466345

Inspection Document #: 708200265

Weld County, CO

NWNW Section 35 T9N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 1.** No wildlife netting observed at day tank.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



Photos 2 & 3. Open excavation/trenching previously identified appears to have been corrected.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 4.** Appears the Operator has removed the trash previously identified.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 5.** Facing north towards the interim areas. Appears the production area has been reduced in size, topsoil have been placed back to its relative position and recontoured. Crews were observed to be performing reclamation activities at the time of this inspection, therefore this is being left “In-Process”.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 6.** Facing northwest from the southeast corner. No apparent stormwater BMPs were identified around the perimeter of the location or around the topsoil stockpile. Blow sand evident and is indicated by red arrow.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 7.** Unused equipment/debris will need to be removed.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 8.** Staff observed that areas being actively reclaimed, and other portions of the location in the northeast corner, had evidence of rill erosion and sediment transport. No apparent stormwater controls were identified on the northeastern portion of the location. More robust stormwater BMPs should be implemented to prevent sediment laden stormwater from entering adjacent lands.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 9.** Continued from previous photo, facing west; See comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



Photo 10. See comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 11.** See comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



Photo 12. See comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 13.** Continued from previous photo; see comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 14.** Continued from Photos 12 and 13; see comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



Photo 15. See comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345




Photo 16. See comments in Photo 8.

Inspection Photos  
Location Name: Boydston 3535  
Location ID: 466345



**Photo 17.** See comments in Photo 8.