

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad - 10/21/2022

Attachment F - Photolog



PHOTO NO 1: PAD FACING SOUTH FROM TOP NORTH CORNER OF TOPSOIL PILE TO NORTHEAST.



PHOTO NO 2: PAD FACING SOUTHWEST FROM CENTER OF PAD.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad

Attachment F - Photolog



PHOTO NO 3: PAD FACING WEST FROM CENTER OF PAD.



PHOTO NO 4: FACING NORTHWEST FROM CENTER OF PAD.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad

Attachment F - Photolog



PHOTO No 5: PAD FACING NORTH FROM CENTER OF PAD.



PHOTO No 6: PAD FACING NORTHEAST FROM CENTER OF PAD.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad  
Attachment F - Photolog



PHOTO NO 7: PAD FACING SOUTHWEST FROM CENTRAL BASE OF TOPSOIL PILE TO NORTHEAST.



PHOTO NO 8: PAD FACING SOUTH FROM CENTRAL BASE OF TOPSOIL PILE TO NORTHEAST.



PHOTO No 9: CENTRAL BASE OF TOPSOIL PILE TO NORTHEAST FROM PAD.



PHOTO No 10: EAST END OF BASE OF TOPSOIL PILE TO EAST FROM PAD.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad

Attachment F - Photolog



PHOTO NO 11: NORTH END OF BASE OF TOPSOIL PILE TO NORTHWEST FROM PAD.



PHOTO NO 12: PAD FACING SOUTHWEST FROM NORTHEAST CENTRAL PAD.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad

Attachment F - Photolog



PHOTO No 13: PAD FACING NORTH FROM NORTH CENTRAL PAD.



PHOTO No 1: VISUAL STAINING ON SIDEWALL OF NORTHERN MOST WELLHEAD. SAMPLE LOCATION OF SS\_WELLHEAD.



PHOTO NO 2: BOTTOM OF TRENCH AT SAMPLE LOCATION SS\_WELLHEAD WHERE VISUAL STAINING WAS OBSERVED.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad  
Attachment F - Photolog




PHOTO NO 3: VIEW OF NEWLY INSTALLED WELLHEADS. LOOKING NORTH.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad  
Attachment F - Photolog



PHOTO NO 4: FAR EASTERN END OF PRODUCTION LINE TRENCHING. SAMPLE LOCATION POINT OF SS\_09.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad  
Attachment F - Photolog



PHOTO NO 5: FULL LENGTH OF PRODUCTION LINE TRENCHING. LOOKING SOUTHEAST.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad  
Attachment F - Photolog



PHOTO NO 6: FULL LENGTH OF PRODUCTION LINE TRENCHING. LOOKING NORTHWEST.



PHOTO No 7: SS\_01 LOCATION. LOOKING NORTHEAST.



PHOTO No 8: SS\_02 LOCATION. LOOKING NORTHEAST.



PHOTO No 9: SS\_03 LOCATION. LOOKING NORTHWEST.



PHOTO No 10: SS\_05 LOCATION. LOOKING SOUTHWEST.



PHOTO No 11: SS\_07 LOCATION. LOOKING SOUTHWEST.



PHOTO No 12: SS\_09 LOCATION. LOOKING SOUTHWEST.

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad – 4/27/2023

Attachment F - Photolog



PHOTO NO 1: FACING SOUTH TOWARD WELLHEADS FROM NORTH CORNER OF PAD



PHOTO NO 2: FACING SOUTHEAST TOWARD WELLHEADS FROM NORTHWEST SIDE OF PAD



PHOTO NO 3: FACING EAST TOWARD FILL PILE FROM CENTER OF PAD.



PHOTO NO 4: FACING SOUTHEAST TOWARD FILL PILE AND EQUIPMENT FROM CENTER OF PAD.



PHOTO NO 5: STOCKPILED CONTAMINATED SOIL PILE



PHOTO NO 6: STORMWATER RETENTION BASIN

# Fulcrum Energy Operating – North Park Basin

Surprise Damfino S6 Pad – 4/27/2023

Attachment F - Photolog

