

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2023

Submitted Date:

05/24/2023

Document Number:

712700211**FIELD INSPECTION FORM**Loc ID 333661 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Overright, Issac		ioverright@maralexinc.com	All SW field inspections
Tahmahkera, Kerry		MaralexTech@gmail.com	Production Technician

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271095	WELL	PR	10/01/2020	GW	067-08915	KEEGAN PRTRICK 33-7-11 #1	PR
294235	WELL	PR	07/02/2008	GW	067-09478	KEEGAN PATRICK 33-7-11 3B	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Present
Corrective Action:	Date: _____

Good Housekeeping:		
Type	OTHER	
Comment:	Observed leak at stuffing box, impacted material on ground. See Photo #1.	
Corrective Action:	Comply with Rule 1002.f.(2).d. Increase maintenance on equipment, cleanup stained material and review self inspection processes.	Date: 06/07/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	And pumpjack, hog wire.	
Corrective Action:		Date:

Equipment:			corrective date
Type: Pump Jack	# 2		
Comment:	One pumpjack not operating (067-09478).		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	gas motor		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" pipe from wellhead to separator.		
Corrective Action:		Date:	

Type: Bird Protectors	# 2		
Comment:	One bird protection cap is missing from the separator. See Photo #2.		
Corrective Action:	Comply with Rule 1002.f.(2).d. Conduct maintenance on equipment, cleanup stained material and review self inspection processes.		Date: 06/07/2023
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	3" pipe from separator to meterhouse. Calibrated within one year.		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 271095 Type: WELL API Number: 067-08915 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 08/09/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 294235 Type: WELL API Number: 067-09478 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 07/26/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: WATER H2OEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Compaction	Pass	Gravel	Pass			

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700215	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124116