

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2023

Submitted Date:

05/23/2023

Document Number:

695108246

## FIELD INSPECTION FORM

 Loc ID 325528 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 96735  
 Name of Operator: WILLIFORD RESOURCES LLC  
 Address: 6506 S LEWIS AVE STE 102  
 City: TULSA State: OK Zip: 74136
**Findings:**

- 7 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	All SW field inspections
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214952	WELL	SI	02/01/2023	OW	067-06557	ANGELINA 1-D	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	PHOTO 1: WELL SIGN/ WEEDS INSIDE PUMPJACK FENCING.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	06/05/2023
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED EQUIPMENT (TBG, PIPE RACKS AND MISCELLANEOUS PIPES AND FITTING NEAR PIPE RACKS AND ON THE NORTH SIDE OF LOCATION).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606. THIS IS THE THIRD NOTICE ON THIS CA IMMEDIATE ACTION IS REQUIRED.	Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Type: Bradenhead	# 1					
Comment:	IS ACCESSABLE					
Corrective Action:					Date:	
Type: Pump Jack	# 1					
Comment:						
Corrective Action:					Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		37.128019,-108.094013
Comment:	THIS TANK BATTERY SERVICES ANGELINA 1-D, 3 AND 2				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	<input type="text"/>

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				
				Date:

**Inspected Facilities**

Facility ID: 214952 Type: WELL API Number: 067-06557 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: WELL LAST PRODUCED 1/1/2023

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/01/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 18 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695108247	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124410">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124410</a>