

Inspection Photos

Loc: 429093

Operator: AUSCO PETROLEUM INC

Inspection Date: 5/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 1. Facing southwest toward the location.



Inspection Photos



Photo 2. The blue frac tank does not have secondary containment and needs to be removed. There is 2 orange buckets that appear to have oil with no labeling and no containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 3. There is an unknown barrel with no labeling or containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 4. Well sign is posted at wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 5. Facing southwest toward the bitcoin equipment at the location.



Inspection Photos



Photo 6. There is a portable secondary containment installed for the 2 chemical totes. The water needs to be removed to allow appropriate freeboard containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 7. The plastic liner has become folded over needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 8. South side of the location facing northeast. The old wattles in this area need to be replaced or removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 9. Facing south at the perimeter ditch. The check dams have filled in with sediment and need to be cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 10. The plastic liner has become folded over needs to be repaired. There are water pump used to hold down the liner and should be removed if not need. Liner should be properly staked down.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 11. It appears in between the equipment there is darkened gravel from a possibly leak.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023

Inspection Photos



Photo 12. Facing northeast toward the bitcoin equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 429093 | Date: 5/22/2023