

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Location #307050				
Corrective Action:					Date:

Paint	
Condition	<input type="text"/>

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

Inspected Facilities

Facility ID: 216891 Type: WELL API Number: 069-06078 Status: SI Insp. Status: WK

Workover

Comment: Initial Bradenhead pressure @ 36 psig, MIRU RMWS e-line, RIH and perforate csg @ 2200' KB 6 SPF for annular squeeze, POOH with spent gun, RIH with CICR and stack out @ 1860' KB, POOH with CICR, inspect CICR and setting tool, attempt to circulate wellbore with rig pump, RD e-line, RIH with tbg to 2200' KB, circulate wellbore clean with rig pump, SB tbg, RU e-line, RIH with CICR and set @ 2175' KB, POOH with setting tool, RDMO e-line, TIH with tbg and stinger, sting into CICR, MIRU Ranger Energy Services cementers, attempts to establish injection rate were unsuccessful, RDMO cementers, SIW, SDFN.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697007577	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125005