

Inspection Photos
Location Name: King-Pyles 4
API: 05-061-06117



1. Belt guard at pumping unit has been moved to inside fenced area



2. Electric panel on REA pole not secured to pole. Fence is installed around REA pole.

Insp #701007009 performed in accordance with Complaint Doc #403326099, 403326120, 403326134