

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2023

Submitted Date:

05/23/2023

Document Number:

701007009

**FIELD INSPECTION FORM**Loc ID 324804 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven D	(303) 893-2438	steve@westernoperating.com	
Hart, Dale	719-688-1638	dale@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212757	WELL	PR	07/01/2021	OW	061-06117	KING-PYLES 4	PR

**General Comment:**

This is an inspection regarding Complaint #403326099, 403326120, 403326134

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Secure electric panel to REA pole

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 212757 Type: WELL API Number: 061-06117 Status: PR Insp. Status: PR**Complaint**

Comment: Regarding Complaint #403326099 - Seal out of the gear box on the pumping unit that's tan oil out on the ground. A shield that's been laying in the pasture for several months. (Inspector found that the belt guard has been moved inside fence around pumping unit. No visible oil was seen on the ground outside of the base of the unit)

Regarding Complaint #403326120 - The cage around an electrical box is open and able to be reached by cattle. The boxes are pulled away from the post. This is both an electrocution concern and a fire concern. (Inspector determined the fence is closed off around the REA pole. However, the electric power box isn't attached to REA pole)

Regarding Complaint #403326134 - An old well site with trash, we'll site sign and rock never cleaned up. (Inspector couldn't locate said trash and sign within the area of the King-Pyles 4 wellsite or tank battery)

Regarding Complaint #403379740 (Submitted 4/20/23) - A month after reporting there is still an electrical panel pulled loose from the pole without an intact cage around it. In a dry season where fire is a concern

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007010	Pictures of submitted complaints	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125496</a>