

Inspection Photos

API: 071-06396

Operator: OGRIS OPERATING LLC

Inspection Date: 5/24/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023

Inspection Photos



Photo 1. Facing west along the reclaimed access road. The perennial vegetation is progressing well along the former road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023

Inspection Photos



Photo 2. Facing southwest. The perennial vegetation is progressing well along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023

Inspection Photos



Photo 3. Facing northwest further along the road. The perennial vegetation is progressing well along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023

Inspection Photos



Photo 4. Facing north along the reclaimed road. There is rock rip/rap installed in the drainages.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023

Inspection Photos



Photo 5. Facing northwest at the location. Vegetation is progressing well at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023

Inspection Photos



Photo 6. Facing north just past the reclaimed wellsite on the reclaimed road. There are noxious weeds (Scotch thistle) in this area that are starting to sprout up.
Lat/Long:37.15370, -104.90250



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06396 | Date: 5/24/2023