

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2023

Submitted Date:

05/25/2023

Document Number:

697007578

FIELD INSPECTION FORM

Loc ID 307109 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 52530
Name of Operator: MAGPIE OPERATING INC
Address: 2707 SOUTH COUNTY RD 11
City: LOVELAND State: CO Zip: 80537

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Donahue, Jessica		jdonahue@ardonenvironmental.com	
Fanning, Trisha		tfanning@ardonenvironmental.com	
Warner, Ross		ross.magpieoil@gmail.com	
Kost, Jody		magpieoil2@yahoo.com	
Jacobson, Eric		eric.jacobson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216891	WELL	SI	07/01/2022	GW	069-06078	WEBER 1	WK

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 216891 Type: WELL API Number: 069-06078 Status: SI Insp. Status: WK

Workover

Comment: Initial Bradenhead pressure @ 38 psig, POOH with tbg and stinger, TIH with new stinger and tbg, unable to sting into CICR, POOH with tbg and stinger, MIRU RMWS e-line, RIH with dump bailer and spot 2 sxs of cement slurry on top of CICR set @ 2200' KB, POOH with dump bailer, RIH and perforate csg @ 1600' KB 6 SPF, POOH with spent gun, circulate wellbore clean with rig pump, RIH with CICR and set @ 1590' KB, POOH with setting tool, RDMO e-line, TIH with tbg and stinger, sting into CICR, unable to open the valve inside of the CICR, POOH with tbg and stinger.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697007579	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126117