

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



**Location Overview: Location is approximately 55 yards from
Parachute Creek
Section/Township/Range: 3 7S96W**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8720 Lack of Stabilization/Compaction on location



Photo # 8721 Lack of Stabilization/Compaction on location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8722 Lack of Stabilization/Compaction on location



Photo # 8723 Lack of Stabilization/Compaction on location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8724 Lack of Stabilization/Compaction on location



Photo # 8727 Lack of Stabilization/Compaction on location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8728 Lack of Stabilization/Compaction on location



Photo # 8730 Lack of Stabilization/Compaction on location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8734 Lack of Stabilization/Compaction on spur road



Photo # 8735 Lack of Stabilization/Compaction on spur road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8736 Lack of Stabilization/Compaction on spur road



Photo # 8737 Lack of Stabilization/Compaction on spur road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8738 Lack of Stabilization/Compaction on spur road




Photo # 8739 Lack of Stabilization/Compaction on spur road

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GM 41-3 pad
Location ID: 323965



Photo # 8740 Lack of Stabilization/Compaction on spur road



Photo # 8741 Lack of Stabilization/Compaction on spur road