

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

05/26/2023

Document Number:

712700221

**FIELD INSPECTION FORM**Loc ID 306861 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270213	WELL	PR	11/25/2003	CBM	067-08898	FEINBERG C 2	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Present](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	<a href="#">Cattle panel</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Cattle panel</a>		
Corrective Action:		Date:	
Type	OTHER		
Comment:	<a href="#">Telemetry, Cattle panel</a>		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	<a href="#">6-ft. chainlink</a>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<a href="#">Cattle panel</a>		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 1		corrective date
---------------------------	-----	--	-----------------

Comment: <a href="#">Telemetry</a>		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: <a href="#">Wellhead</a>			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: <a href="#">3" line from separator to meterhouse.</a> <a href="#">Calibrated within one year.</a>			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment: <a href="#">3" line from wellhead to separator.</a>			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: <a href="#">gas motor</a>			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	OTHER		37.270210,-107.537800
Comment: <a href="#">Partially buried steel tank.</a>					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date: <input type="text"/>
<b><u>Venting:</u></b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date: <input type="text"/>
<b><u>Flaring:</u></b>		
Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities									
Facility ID:	270213	Type:	WELL	API Number:	067-08898	Status:	PR	Insp. Status:	PR
BradenHead									
Date of Last Brhd Test:		08/16/2022		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:		<div></div>							
Corrective Action:		<div></div>						Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil containers within spill containment.
Rip Rap	Pass	Ditches	Pass			
Waddles	Pass	Check Dams	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: [Minimal erosion and sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700226	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126649">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6126649</a>