

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2023

Submitted Date:

05/26/2023

Document Number:

707601273

FIELD INSPECTION FORMLoc ID 305968 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284106	WELL	SI	02/01/2023	OW	123-23751	ERICKSON A 8-17	PR

General Comment:

This is a WELL inspection. (AMI: Alternate Method Inspection).
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 6 Location IDs
(306018, 305967, 305968, 305969, 306012, 330150).
(Well(s): 6: Producing | PR).

Refer to Field Inspection Report doc. #707601127 and/or Location ID #306018
for Battery / Facility, Equipment info.

*Follow-up to Field Inspection Report doc. #707601131 dated 04/20/2023.

*Response to Field Inspection Report Resolution (FIRR) doc. #403406499 dated 05/18/2023.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Wellsite sign NOW posted.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<p>Prior FIR: Sign w/ Emergency number NOT posted at wellsite. Refer to Rule 605.d for guidance. *Post sign w/ Emergency number at wellsite. Comply with Rule 605.d. Corrective Action date: 05/24/2023. (30-days). See photo #1. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>This FIR: **Sign w/ Emergency number NOW posted at wellsite. See photo #2. (Operator provided).</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:			Date:	
Equipment:				
			corrective date	
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 0			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				

Corrective Action:					Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.505620,-104.573720	
Comment:		Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150). (Well(s): 6: Producing PR).				
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	284106	Type:	WELL	API Number:	123-23751	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	02/21/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 05/25/2023 at approximately 09:00 hrs. I, Bret Evins, conducted an AMI: Alternate Method inspection at: Operator Name: NOBLE ENERGY INC Location Name: ERICKSON A-66N64W/8NENE Location ID: 305968 Well Name(s): Erickson A 8-17. API: 123-23751. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150). (Well(s): 6: Producing PR).</p> <p>Refer to Field Inspection Report doc. #707601127 and/or Location ID #306018 for Battery / Facility, Equipment info.</p> <p>*Follow-up to Field Inspection Report doc. #707601131 dated 04/20/2023. *Response to Field Inspection Report Resolution (FIRR) doc. #403406499 dated 05/18/2023.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Sign w/ Emergency number NOT posted at wellsite. Refer to Rule 605.d for guidance. *Post sign w/ Emergency number at wellsite. Comply with Rule 605.d. Corrective Action date: 05/24/2023. (30-days). See photo #1. **Sign w/ Emergency number NOW posted at wellsite. See photo #2. (Operator provided).</p> <p>Field Inspection Report Resolution FIRR doc. #403406499 indicates 1.) Sign w/ Emergency number posted at wellsite as of 05/11/2023.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/26/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601274	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6127155