

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2023

Submitted Date:

05/27/2023

Document Number:

707601277

FIELD INSPECTION FORMLoc ID 431798 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state. co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431796	WELL	SI	11/01/2018	OW	123-36782	BETHYL GW 29-12	PA

General Comment:

This is a PLUGGED & ABANDONED WELL inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing. Initial plugs.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.628560 / -104.467800

Well GPS coordinates: 40.629892 / -104.465929

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 431796 Type: WELL API Number: 123-36782 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: A-Plus

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 8746'-6725'Cement Volume (sx): 2 sxsGood Return During Job: YESCement Type: Class "G" Neat 15.8#Comment:

Workover Contractor: A-Plus Well Services, Rig #12.
Cement Contractor: A-Plus Well Services.

Reference:

Form 6N on file. Notice of Intent to Abandon date: 05/15/2023. Approved.

Form 42 on file. Notice of MIRU. Start Date: 05/25/2023. Approved.

Form 42 on file. Notice of Plugging Operations. Start Date: 05/25/2023. Approved.

2023/05/26:

Plugging Operations: Cementing. Initial plugs.

2023/05/26: JSA attached as photo to this report.

SAFETY/JSAMEETING, CHECK PSI, CSG O PSI, TBG 25 PSI, SURFACE O PSI, TOO H
LO 28 JTS, RUWL, PU & SET 71N 26# 10 KCIBPAT 8745, PU 3.125 DUMP BAILER &
SPOT

2 SACS 15.8# G-NEAT CMT @1.15 YIELD ON PLUG 8745-8736, LOAD W/48 BBLS &
TEST CSG TO 1500, HAD GOOD TEST PU & SET 71N 26# 10KCIBPAT 6725, RDWL,
SWI.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 05/26/2023 at approximately 13:09 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: BETHYL GW /29-12 Location ID: 431798 Well Name(s): Bethyl GW 29-12. API: 123-36782. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing. Initial plugs. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.628560 / -104.467800 Well GPS coordinates: 40.629892 / -104.465929</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/27/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601279	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6127875