

Well Name: Carpenter 32-6-3 2/Carpenter 32-6-3 15
Document Number: 712700091
Inspector: Curtis Pattillo

Location ID 438700

Installed wattles along eastern side of location berms must be maintained or removed. Previous inspection on 1/11/2022 required the installation of BMPs and spot seeding. The area has not been stabilized, reseeding as not been successful. Contact the SW Reclamation Specialist Ryan Costa regarding interim reclamation. See Photos #2 & #3.

Correction Action Due: 5/5/2023

Action Taken: Contacted SW Reclamation Specialist Ryan Costa regarding interim reclamation. Currently attempting to contact landowner to get permission to fence location to keep livestock away from reclamation areas. Plan to re-seed once permission is received to fence off location. Installed new wattles/repositioned existing wattles surrounding location.

