

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2023

Submitted Date:

05/23/2023

Document Number:

712700209**FIELD INSPECTION FORM**Loc ID 333963 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections
Overright, Issac		ioverright@maralexinc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
,		maralextech@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276035	WELL	PR	10/27/2005	CBM	067-09016	KEEGAN PATRICK 33-7-11 2A	PR
298720	WELL	PR	02/09/2009	CBM	067-09631	KEEGAN PATRICK 33-7-11 3C	PR

General Comment:[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Present		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Observed lube oil leak from the stuffing box at both wellheads. Impacted material on ground. See Photos #4 & #6.		
Corrective Action:	Comply with Rule 1002.f.(2).d. Increase maintenance on equipment, cleanup stained material and review self inspection processes.		Date: 06/07/2023
Type	WEEDS		
Comment:	Observed CO-State Class B listed weed species (Musk thistle) across northeast corner of well site. See Photo #2.		
Corrective Action:	Comply with Rule 606. Control weeds.		Date: 06/06/2023
Type	UNUSED EQUIPMENT		
Comment:	Observed sucker rods stored on ground at pumpjack. See Photo #5.		
Corrective Action:	Comply with Rule 606. Return to service or remove if not needed for ongoing oil and gas operations.		Date: 07/24/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:	gas motor		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:	Sound abatement walls on one pumpjack.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	3"pipe from separator to meterhouse. Calibrated within one year.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			

Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" pipe from wellhead to separator.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Observed one bird protection cage missing from separator vent stack.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 276035 Type: WELL API Number: 067-09016 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 08/09/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 298720 Type: WELL API Number: 067-09631 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 07/26/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: WATER H2OEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403411647	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124123
712700213	Well Loaction Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124113