

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2023

Submitted Date:

05/24/2023

Document Number:

690204254

FIELD INSPECTION FORM

Loc ID 429093 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	
Hart, Tim		thart@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429093	LOCATION	AC			-	Pathfinder C 11-12 1	RI

General Comment:

On 5/22/2023, Ryan Costa conducted a location and stormwater management inspection. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:	There are some containers with no labeling.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/24/2023

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	_____
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	There are several water pumps that do not appear to be in use and need to be removed. All unused equipment and supplies not needed must be removed.		
Corrective Action:	Comply with 606.	Date:	06/24/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are degraded wattles at the south at west perimeter of the location that need to be replaced or removed. There are rock check dams at south side of the location that need maintenance. There are some buckets and barrels that need to be stored in containment. There is also an area of darkened gravel from a possible spill by the cooling units. The plastic liner at the cooling units has folded over and needs to be repaired.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Implement or modify BMPs for improved material handling and spill prevention.

Date: 05/26/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403412734	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124961
690204255	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6124954