

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN-66S94W /34SESW

Location ID: 323986



Photo #129 From entrance to location.



Photo #130 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN-66S94W /34SESW

Location ID: 323986



**Photo #136 Calibration cards not conspicuously posted.**



**Photo #133 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN-66S94W /34SESW

Location ID: 323986



**Photo #137 Location lacks stabilization**



**Photo #138 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN-66S94W /34SESW

Location ID: 323986



**Photo #140 -Insufficient tracking BMP at entrance to location. To minimize the transport of sediment**