

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2023

Submitted Date:

05/31/2023

Document Number:

699106753

**FIELD INSPECTION FORM**

Loc ID 465146 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
 Name of Operator: PDC ENERGY INC  
 Address: 1099 18TH STREET SUITE 1500  
 City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>
Revas, Robbie		robbie.revas@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465146	LOCATION	AC			-	Rio LC Pad	AC
465152	WELL	DG	02/01/2023	LO	001-10464	Rio 22C	DG

**General Comment:**

[This is a follow up to prior inspection document #699106732.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Sound Walls		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 465146 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Well Drilling**

**Rig:** Rig Name: True 41 Pusher/Rig Manager: Eric Cherry  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_  
 Comment: Active operation  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 465152 Type: WELL API Number: 001-10464 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: True Rig 41 Pusher/Rig Manager: Eric Cherry  
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: Waste Connections/ Pawnee  
 Comment: While there, I observed a drilling operation taking place. At the time of inspection they were on the Rio 22C. Currently at a drilled depth of 9157'.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Wednesday 5-31-2023 at approximately 0751hrs, I, Inspector Adam Burns, conducted an on-site inspection to prior inspection document #699106732 at Rio LC Pad of PDC Energy, at Location ID #465146 in Adams, County Colorado.                      While there, I observed that PDC had a mitigation plan of setting hay bales on the east side of the sound walls. See attached photo                      During this inspection the CA has been corrected                      This is a summary of the inspection report.</p>	burnsa	05/31/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106754	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6130218">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6130218</a>