

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2023

Submitted Date:

05/25/2023

Document Number:

690204236

FIELD INSPECTION FORMLoc ID 324795 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	
Hart, Dale	719-688-1638	dale@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212650	WELL	SI	01/01/2022	OW	061-06010	FOSTER 1	RI

General Comment:

On 5/15/2023, Ryan Costa conducted a reclamation inspection of the Foster #1 wellsite.
See attached photos and additional details within this report.

Environmental**Spill/Remediation:**

Comment: It appears there was a historic spill that occurred northwest from the tank battery that extends approximately 750'. There are also impacted areas north of the wellsite shown in photo 1. Operator will need to submit a form 27 to investigate and sample soils per Rule 913.

Corrective Action: Submit Form 27 Remediation Plan to investigate soil impacts impeding vegetation growth.

Date: 05/31/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
It appears the wellsite location is in process of being decommissioned. A form 6 notice to plug and abandon the well is in process. The tank battery has been removed but there are still pipe risers and other equipment that remain. All equipment will need to be removed within 3 months of plugging the well.	CostaR	05/25/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403413754	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125844
690204237	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6125833