

**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NENW**  
**Location #: 335171**



**Photo #158 From entrance to location.**



**Photo #160 from entrance to location**



**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NENW**  
**Location #: 335171**



**Photo #162 Cut slope lacks stabilization.**



**Photo #163 Cut slope lacks stabilization**



**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NENW**  
**Location #: 335171**



**Photo #164 Run on to location is not being controlled.**



**Photo #165 Run on to location is not being controlled.**



**Stormwater Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NENW**  
**Location #: 335171**



**Photo #169 Rocks and sediment encroaching on tank containment.**



**Photo #170 Rocks and sediment encroaching on equipment.**