

Interim Reclamation and Stormwater Inspection

Date: 05/26/2023

Operator: FUNDARE RESOURCES OPERATING
COMPANY LLC - 10773

Location ID: 431782

Inspection Document #: 708200286

Weld County, CO

NESW Section 27 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Close up photo of undesirable species (e.g. kochia) observed throughout the interim reclamation areas. The Operator will need to manage the location for undesirable weed species during the growing season.

Inspection Photos
Location Name: Razor 27K-3407A
Location ID: 431782



Photo 2. Southern portion of location. Degraded straw wattles are now considered debris and will need to be removed.

Inspection Photos
Location Name: Razor 27K-3407A
Location ID: 431782



Photo 3. Southern interim area. The interim areas are not progressing towards reclamation standards with evidence of non-uniform vegetation cover resulting in areas of bare soil and undesirable vegetation (e.g. kochia) was observed growing throughout. Additional reclamation activities are required in order to meet Rule 1003 standards.

Inspection Photos
Location Name: Razor 27K-3407A
Location ID: 431782



Photo 4. Eastern interim areas; see comments in Photo 3.

Inspection Photos
Location Name: Razor 27K-3407A
Location ID: 431782



Photo 5. Northern interim areas; see comments in Photo 3.

Inspection Photos
Location Name: Razor 27K-3407A
Location ID: 431782



Photo 6. Western interim/topsoil stockpile area; see comments in Photo 3.

Inspection Photos
Location Name: Razor 27K-3407A
Location ID: 431782



Photo 7. Tumbleweed accumulations around flare unit will need to be removed as they present a fire hazard.