

Inspection Photos

API: 055-06012

Operator: OXY USA INC

Inspection Date: 6/1/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 2. There is still stained soil at the pipe outlet. Previous corrective action was not completed. There is also insulation debris that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 3. Facing toward the produced water tank. The secondary berm around the tank is insufficient to contain a spill. Red arrow points to small berm which could easily be overtopped by a leak. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 4. Facing northwest at the location. The remediation area where tank was located remains open and the safety fence is in disrepair. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 5. Facing where tank was located which remains an open excavation due to active remediation. Stormwater has filled in the open excavation. Safety fence is in disrepair. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos




Photo 6. Facing northwest toward the excavated area which has been backfilled. There are noxious weeds shown at red arrow and the disturbed soils need to be recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 7. Facing southeast at the down gradient portion of the location. The degraded perimeter wattles were removed however, no new BMP's were installed and there is a creek approximately 10ft' from the edge of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 8. Facing southwest at the location. All disturbed unused areas of the location need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 9. Facing southeast further away from the location. There is a degraded perimeter fence that needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 10. Standing approximately 125' northwest of the location along the flowline area is an eroded out culvert where the creek flows. The culvert needs repaired or removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 11. Standing at the east side of the location. The perimeter fence around the location is not maintained and would be beneficial to prevent livestock entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 12. There are noxious weeds along the access road that will soon be seeding out and need to be controlled. Red arrows point to Houndstongue and Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 6/1/2023

Inspection Photos



Photo 13. Observed along the access road were several dilapidated snow fences which need to be removed or repaired.

