

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Location Overview: Location is approximately 529 yards from
West Mamm Creek
Section/Township/Range: 8 7S92W**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9271 Lack of stabilization/compaction
/insufficient BMP's on location**



**Photo # 9272 Lack of stabilization/compaction
/insufficient BMP's on location**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9273 Lack of stabilization/compaction
/insufficient BMP's on location**



**Photo # 9274 Lack of stabilization/compaction
/insufficient BMP's on location**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9275 Lack of stabilization/compaction
/insufficient BMP's on location**



**Photo # 9277 Lack of stabilization/compaction
/insufficient BMP's on location**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9278 Lack of stabilization/compaction
/insufficient BMP's on location**



**Photo # 9279 Lack of stabilization/compaction
/insufficient BMP's on location & lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9280 Lack of stabilization/compaction
/insufficient BMP's on lease road**



**Photo # 9281 Lack of stabilization/compaction
/insufficient BMP's on lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9282 Lack of stabilization/compaction
/insufficient BMP's on lease road**



**Photo # 9283 Lack of stabilization/compaction
/insufficient BMP's on lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9284 Lack of stabilization/compaction
/insufficient BMP's on lease road**



**Photo # 9286 Lack of stabilization/compaction
/insufficient BMP's on lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC D8E Pad
Location ID: 334839



**Photo # 9287 Lack of stabilization/compaction
/insufficient BMP's on lease road**