

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2023

Submitted Date:

06/02/2023

Document Number:

690204279

FIELD INSPECTION FORM

Loc ID 333348 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 66561
Name of Operator: OXY USA INC
Address: PO BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
NEWVILLE TONI		toni_newville@oxy.com	
OXY		COGCCInspections@Oxy.com	
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
333348	LOCATION	AC			-	Sheep Mountain Unit - Drill Site 3 047683X	RI

General Comment:

On 6/1/2023, Ryan Costa conducted a follow up inspection at the Drill Site 3 compressor facility. See attached photos and additional details within this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Did not observed trash during this inspection.		
Corrective Action:			Date:
Type	WEEDS		
Comment:	There were some noxious weeds (Diffuse knapweed) found at the north and northwest side of the location that will need to be controlled.		
Corrective Action:	Comply with Rule 1003.f.		Date: 06/16/2023

Overall Good:

Spills:

Type	Area	Volume	
Comment:	Previous inspection observed a leak that had occurred at the compressor which sprayed offsite to the northeast. A form 19 spill report was submitted since previous inspection. There are still stained soils on location at the east side of the compressor and to the northeast that drifted off the location. There was blackened soils and vegetation with a hydrocarbon odor. Stained soils have not been cleaned up and there was no containment BMP's at the impacted area. There have been stormwater events since previous inspection which have likely transported contaminated material further out. Previous corrective action has not been completed.		
Corrective Action:	Immediately Control and contain spills/releases and clean up per Rule 912.a.		Date: 04/12/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204280	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133890