

Inspection Photos

API: 055-06105

Operator: OXY USA INC

Inspection Date: 6/1/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 1. Facing southeast ascending the hill toward the location. Grading has pushed out material into a berm which is creating more of a disturbance and not allowing stormwater to be diverted off the road. There is a long stretch of the road where stormwater will be directed down the road which will cause erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 2. Facing southeast ascending the hill toward the location. Stormwater is not diverted off the road and the an erosion channel is beginning to develop.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 3. Facing southeast ascending the hill toward the location. The road has been widened along this area which will create more stormwater impact. Disturbance area of the road needs to be minimized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 4. Facing northwest at the location. Most of the unused equipment and debris were removed however there is still cement debris and other unused equipment that remains. Previous corrective action is not complete.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 5. There is a white powder substance spill on the ground that needs to be cleaned up. Yellow arrow in previous photo shows the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 6. Facing back southeast at the location. The bare soil will need to be reseeded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023

Inspection Photos



Photo 7. Facing back southeast at the location. There is a bent electric utility at this site that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 6/1/2023