

Inspection Photos

API: 055-06067

Operator: OXY USA INC

Inspection Date: 6/1/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023

Inspection Photos



Photo 1. Facing northwest along the access road. This cattle guard has filled in with sediment and is obstructing stormwater flow along the right side of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023

Inspection Photos



Photo 2. Stormwater is not being properly diverted and is causing erosion across the road transporting sediment offsite shown in the next photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023

Inspection Photos



Photo 3. There is erosion of the road side occurring in this same area of previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023

Inspection Photos



Photo 4. The flowline disturbance area was reseeded last year but vegetation does not appear to be establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023

Inspection Photos



Photo 5. There is erosion occurring on the access road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023

Inspection Photos



Photo 6. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 6/1/2023