

# Inspection Photos

API: 055-06102

Operator: OXY USA INC

Inspection Date: 6/1/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06102 | Date: 6/1/2023

## Inspection Photos



**Photo 1.** Facing northeast toward the wellsite. There is a large excavation around the wellhead has been fenced off to prevent entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06102 | Date: 6/1/2023



## Inspection Photos



**Photo 2.** There is a large excavation around the wellhead approx. 15ft deep by 15'w. The wellhead will need to be cut an capped far enough below grade to allow proper recontouring.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06102 | Date: 6/1/2023



## Inspection Photos



**Photo 3.** There is a lined pit adjacent to the well which does not appear to have any use and needs to be closed per 1004 Rules.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06102 | Date: 6/1/2023

## Inspection Photos



**Photo 4.** Facing north at the location. It appears impacted soils were removed and road base material has been hauled in shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06102 | Date: 6/1/2023



## Inspection Photos



**Photo 5.** Taken during previous inspection on 4/10/2023. Drone aerial photo facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06102 | Date: 6/1/2023