

Inspection Photos

API: 055-06041

Operator: OXY USA INC

Inspection Date: 6/1/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 1. Facing southwest along the access road near the SMU #1-12-B . There is sediment from the road depositing in this area off the road causing additional disturbance. BMP's such as a sediment trap should be installed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 2. Facing southwest along the access road near the SMU #1-12-B . The is erosion occurring along the access road and no BMP's were installed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 3. Facing southwest further along the access road. There is erosion occurring along the access road and no BMP's were installed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 4. Facing back to the northeast. The road is directing stormwater all the way down the road causing erosion. No BMP's have been installed to direct stormwater off the road and reduce stormwater concentration along the road. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 5. Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 6. Facing back northeast along the access road. Stormwater is directed all the way down the length of the road with no BMP's to divert and control stormwater. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 7. Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023

Inspection Photos



Photo 8. Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/1/2023