

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2023

Submitted Date:

06/05/2023

Document Number:

694500574

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ NEIDEL, KRIS \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 95960

Name of Operator: WEXPRO COMPANY

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Billy Ginn		William.Ginn@Hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412315	PIPELINE	AC	12/15/2022		-	HIAWATHA GATHERING PIPELINE SYSTEM	EI

**General Comment:**

On 5/30/2023 COGCC staff, Kris Neidel inspected Spill 484529 at Facility 120692. Weather; 65 degrees and dry at the time of inspection, Moisture was observed in the area around this location, indicating rain had fallen in the recent past. The spill was discovered while hydro excavating to add a line to a dehy. While trenching some of the trench cuttings were placed on the south end of the facility pad. Some stained soil (grey) was observed in the excavation. Water was present in the excavation, COGCC Staff was told that the water was from recent rain, no rainbow was observed on pooled water.

Corrective Actions: Impacted Soil should be removed and soil samples collected for Table 915-1. Overburden from trench should be sampled for Table 915-1. should provide notice to Environmental staff, Kris Neidel (kris.neidel@state.co.us) or 970-846-5097 72hrs prior to mobilization at beginning of all sampling events.



**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings				
Comment				
Corrective Action				Date:

**Spill/Remediation:**

Comment: [The spill was discovered while hydro excavating to add a line to a dehy.](#)

Corrective Action: [Impacted Soil should be removed and soil samples collected for Table 915-1. Overburden from trench should be sampled for Table 915-1. should provide notice to Environmental staff, Kris Neidel \(kris.neidel@state.co.us\) or 970-846-5097 72hrs prior to mobilization at beginning of all sampling events](#)

Date: 07/05/2023

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500575	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6135751">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6135751</a>