

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Entrance to location



Open end tank valves. Debris

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Open end tank valve. Debris



Leaking equipment. Stained equipment and soils

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Debris



Stained soil

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Oil leak. Stained equipment and soil



Oil leak. Stained equipment and soil

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Sign at wellhead missing required information



Lacking freeboard capacity

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



No Pit ID registration



Unused equipment

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Unused equipment



Stained soil

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Open end loadlines



No bird protection

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Debris



Unidentified chemical drums. Open to wildlife



**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Open to wildlife



Unidentified tank missing required labels

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Unused equipment open to wildlife



Debris

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Flowline leak? Spill reported?



Debris and oil residue

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Oil residue along pit



Oil residue and debris

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Location from Southwest corner



Location from Northwest corner

**Antler Energy LLC
Ross-Government-USA 43-7
Location #312970**



Location from Northeast corner



Location from Southeast corner

Antler Energy LLC
Ross-Government-USA 43-7
Location #312970

Description

Description