

Inspection Photos

API: 055-06195

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/6/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023

Inspection Photos



Photo 1. Facing south toward the location. There is sparse perennial vegetation at the location but also a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023

Inspection Photos



Photo 2. Facing east toward the location. There is sparse perennial vegetation at the location but also a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023

Inspection Photos



Photo 3. Facing southeast toward the location. There is sparse perennial vegetation at the location but also a reduction in noxious weeds was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023

Inspection Photos



Photo 3. Facing toward the southside of the location. There is more vegetation establishment at the side of the location but is still not 80% of reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023

Inspection Photos



Photo 5. Center of the location facing north. There is some plastic debris that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023

Inspection Photos



Photo 6. Facing southeast at the surrounding undisturbed vegetation which consists of Western wheat, Needle and thread grass, Sand drop seed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/6/2023