

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2023

Submitted Date:

06/07/2023

Document Number:

708300544

FIELD INSPECTION FORMLoc ID 334716 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------|
| , TEP | | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 259724 | WELL | PR | 09/28/2001 | GW | 045-07774 | UNOCAL GM 240-1 | PR |
| 264291 | WELL | PR | 01/13/2003 | GW | 045-08204 | WILLIAMS GM 41-1 | PR |
| 264292 | WELL | PR | 01/13/2003 | CBM | 045-08205 | WILLIAMS GM 341-1 | PR |
| 291035 | WELL | PR | 06/13/2007 | GW | 045-14262 | WILLIAMS GM 344-36 | PR |
| 291036 | WELL | PR | 06/13/2007 | GW | 045-14261 | WILLIAMS GM 441-1 | PR |

General Comment:**COGCC Inspection Report Summary**

On 6/6/2023 at approximately 15:30, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWN at Location ID #334716 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Gas meter calibration record not conspicuously posted

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|---|-------|--|
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 3 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|--|------------------|
| Type: Gas Meter Run | # 5 | |
| Comment: | Gas meter calibration record not conspicuously posted | |
| Corrective Action: | Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2). | Date: 06/17/2023 |
| Type: Horizontal Heated Separator | # 5 | |
| Comment: | | |
| Corrective Action: | Date: | |
| Type: Plunger Lift | # 5 | |
| Comment: | All wells on plunger lift | |
| Corrective Action: | Date: | |
| Type: Bradenhead | # 5 | |
| Comment: | No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible. | |
| Corrective Action: | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 200 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Centralized containment | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|------------------------|-------------------------|-------|--|
| Comment: | Centralized containment | | |
| Corrective Action: | | Date: | |
| <u>Venting:</u> | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| <u>Flaring:</u> | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 259724 | Type: | WELL | API Number: | 045-07774 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 264291 | Type: | WELL | API Number: | 045-08204 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 264292 | Type: | WELL | API Number: | 045-08205 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 291035 | Type: | WELL | API Number: | 045-14262 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 291036 | Type: | WELL | API Number: | 045-14261 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | | | | | | |
| Compaction | | | | | | |
| | | Sediment Traps | | | | |
| Berms | | | | | | |
| | | Culverts | | | | |
| | | Ditches | | | | |
| | | Gravel | | | | |
| | | Berms | | | | |
| | | Rip Rap | | | | |
| Gravel | | | | | | |

Comment: Light gravel and compaction on location; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 708300545 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6139343 |