

Interim Reclamation and Stormwater Inspection

June 6, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 336152

Inspection Document #: 697504704

Weld County, CO

SENW Section 34 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Drone aerial imagery illustrates the interim reclamation area for the HSR-Vadney location, a portion of the associated access road, and the Lorraine Adams property (red arrows). Photo illustrates weed management is being performed around the wellhead and Lorraine property (orange polygon), but the remainder of the interim area consists mostly of Common rye and Cheatgrass was observed in patches but more persistent south of the wellhead (reddish vegetative color). Smooth brome has established along portions of the northern interim area but has diminished around the wellhead and south of the wellhead where Cheatgrass was observed.



Inspection Photos
Location Name: HSR-VADNEY
Location ID: 336152




Photo 2. Photo illustrates approximate locations of handheld photos.

Inspection Photos
Location Name: HSR-VADNEY
Location ID: 336152



Photo 3. Photo taken from the northeastern area, facing West. Photo illustrates the current vegetation which is predominantly undesirable annual vegetation, Common rye.

Smooth brome was observed in small patches along the north-central and northwestern interim areas.



Photo 4. Photo taken north of the wellhead, facing East. Photo illustrates the area that was described in Photo 1 as being actively managed for weeds.

Note- there has been a decrease in Smooth brome within this actively managed area.



Inspection Photos
Location Name: HSR-VADNEY
Location ID: 336152



Photo 5. Photo taken north of the wellhead, facing South. See comments under Photo 4.



Photo 6. Photo taken south of the wellhead, facing South. Photo illustrates an area of cheatgrass establishment. It appears this area has decreased in Smooth brome presence.

Inspection Photos
Location Name: HSR-VADNEY
Location ID: 336152



Photo 7. Photo taken south of the wellhead, facing West. See comments under Photo 6.



Photo 8. Photo taken south of the wellhead, facing North. See comments under Photo 6.



Inspection Photos
Location Name: HSR-VADNEY
Location ID: 336152



Photo 9. Photo taken from the associated offsite tank battery. Photo illustrates weed debris around equipment that appears to have blown in from the surrounding area.



Photo 10. Photo taken from the associated offsite tank battery. See comments under Photo 9.



Inspection Photos
Location Name: HSR-VADNEY
Location ID: 336152



Photo 11. Photo taken from the associated offsite tank battery. Photo illustrates tape that is degrading. Tape and foam coming off piping, which is contributing to trash around the location.



Photo 12. Photo taken from the associated offsite tank battery. Photo illustrate unused equipment being stored within secondary containment.

